


PX1091	6

Mounting bracket for M8Mounting bracket for M12Mounting bracket for M12Mounting bracket for M16Mounting bracket for M18BES 08-HW-1BES 12-HW-1BES 16-HW-1BES 18-HW-1 Description Ordering code

18:1











Mounting bracket for M24 Mounting bracket for M30 Mounting bracket for M36 BES 24-HW-1

BES 30-HW-1





These aluminum mounting brackets provide a way of easily and quickly attaching sensors to the machine.

For tubular sensors we recommend the additional use of clamps (see pages 6.20 and 6.21).

